



# Imperial Fastener Company, Inc.

Cubicle Tracks • Cubicle Curtains • Intravenous Support Systems

## **Apollo Cloth Care Instruction**

### **Laundering:**

Machine wash maximum temperature of wash 30° Celsius (86° Fahrenheit); do not use chlorine-based bleach; iron at maximum sole-plate temperature of 140° Celsius (284° Fahrenheit); Tumble dry under 70° Celsius (58° Fahrenheit); Professional dry cleaning recommended.